



Specification Sheet

Application Method	Number of Coates	Coating Thickness
Brushed On with Paint Brush	Apply 1 - 2 heavy coats. Allow 2 hours between coats.	A minimum dry film thickness of 55 - 75 microns must be achieved

PLEASE NOTE: Before applying Action Clear Xtreme product on pre-rusted surfaces, always clean the surface by wiping down with general purpose thinners to remove grease and dirt, leaving a clean dry surface.

If rust is present, it should be removed before applying Action Clear Xtreme. For best results use a wire brush to remove rust flakes. Then apply Action Gel to remove remaining rust and restore the metal surface. Finally wipe down with general purpose thinners before applying the Action Clear Xtreme.

Before the use of Action Clear Xtreme, a test should be undertaken on an inconspicuous area to ensure the desired result.